060101

Note: The exam has 5 questions, for a total of 120 points. Explain your answer and write down the necessary details of your calculation. No explanation/details = No credits. *Good Luck!*

Some definitions and function values for your reference:

- $(x) = P[Z \ x] = \sum_{x}^{x} (t) dt$, cdf of a standard normal random variable $Z \ N(0, 1)$.
- $(x) = \frac{1}{2}e^{-x^2/2}$, pdf of a standard normal r.v.
- (1.96) = 0.975, (1.645) = 0.95, (1.282) = .90.
- 1. We are interested in a quality characteristic which can be assessing through a \bar{x} chart for a normal mean. If the mean shifts from the in-control value–say, μ_0 –to another value $\mu_1 = \mu_0 + k$. Recall that $\bar{X} = N(\mu, 2)$. The control limits are UCL= $\mu_0 + L \neq \overline{n}$ and LCL= $\mu_0 L \neq \overline{n}$
- (10) (a) Find -risk, i.e. the probability of *not* detecting this shift (from μ_0 to μ_1) on the first subsequent sample.
- (10) (b) Find the ARL (Average Run Length) before this shift is detected.
- (10) (c) Does smaller ARL indicate a better control chart? Comment and discuss briefly.
- (10) 2. An \bar{x} chart is used to control the mean of a normally distributed quality characteristic. It is known that = 6.0 and n = 4. The center line=200, UCL=209, LCL=191. If the process mean shifts to 188, find the probability that this shift is detected on the first subsequent sample?
- (20) 3. In many process control problems, we can sometimes transform a quality characteristic of variable into one of attribute. Give 2 examples such that one is appropriate and the other is inappropriate. Discuss and comment briefly.

Serial Data Analysis 2005 Guide: C. Andy Tsao

060101

Let J(F) = E [e